revised 4/27/2009 2:55 PM



# FACILITY COMPLIANCE AUDIT REPORT

## Division of Waste Management Solid Waste Section

UNIT TYPE: (check all that apply to this audit with same Permit number)														
Lined MSWLF		LCID	X	YW		Transfer		Compost		SLAS		COUNTY: Edgecombe		
Closed MSWLF		HHW		White goods		Incin		T&P		FIRM		PERMIT NO.: 33F		
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF		FILE TYPE: COMPLIANCE		

Date of Audit: 2/9/2009. Date of Last Audit: 1/9/2008

#### **FACILITY NAME AND ADDRESS:**

BARNHILL CONTRACTING ROCKY MOUNT ASPHALT PLANT PO BOX 1529 TARBORO NC 27886 HWY 97E

FACILITY CONTACT NAME AND PHONE NUMBER: Phone 252 824 8235, mobile 813 6200 Buddy Rose

Fax 252 824 8276 email: brose@barnhillcontracting.com

**GPS COORDINATES:** (Decimal Degrees) N: 35.98618 <u>E</u>: 77.74920

#### **AUDIT PARTICIPANTS:**

Ben Barnes NCDENR Solid Waste Section Buddy Rose Barnhill Contracting

### **STATUS OF PERMIT:**

Expired, permit issued October 29, 1998 was due for review on or before October 29 2003

#### **PURPOSE OF AUDIT:**

To conduct a comprehensive audit of a permitted LCID facility

#### **NOTICE OF VIOLATION(S) (citation and explanation):**

None

You are hereby advised that, pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Statute or Regulations. If the violation(s) noted here continue, you may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

#### **STATUS OF PAST NOTED VIOLATIONS (List all noted last audit):**

None

#### **OTHER COMMENTS / SUGGESTIONS:**

- 1) Operator is conducting annual inspections of the site.
- 2) Make sure all erosion control devices are inspected weekly.
- 3) Make sure that the annual inspection is conducted of the perimeter of the site for any indication of methane disturbances
- 4) Some incidental non-conforming waste on site.
- 5) Impounded water on top of the site needs to be drained and area sloped so that water does not stand on surface.

# FACILITY COMPLIANCE AUDIT REPORT

### Division of Waste Management Solid Waste Section

Page	2	$\alpha f$	
rage	_	UΙ	_

6) Make sure that all waste including side slopes is covered every 30 days.										
Please contact me if you have any questions or concerns regarding this audit report.										
(signature) Phone: 919 621 3680  Regional Representative										
Ben Barnes, Environmental Senior Specialist, Solid Waste Section										
Delivered on :April 27, 2009 by		hand delivery	X	email		Certified No. []				

cc: Mark Poindexter, Field Operations Branch Head Dennis Shackelford, Eastern District Supervisor Donald Herndon, Compliance Officer Wendy McNeil, Solid Waste Section Supervisor